Information Sheet



EFFECTIVE MEANS OF CLEANING & MAINTAINING METLAM HAND DRYERS Quick & easy tips for keeping the product looking great and working well

Retaining a great finish on Metlam Hand Dryer surfaces is just a matter of a few simple steps. And you don't need any expensive cleaning agents or special equipment – ordinary household cleaners are usually all that's required. You just need to bear in mind a few easy DOs and DON'Ts ...

KEEPING STAINLESS STEEL, ZINC ALLOY DIECAST & ABS CLEAN

* Metlam Hand Dryers can looks best if it's cleaned regularly with plenty of water.

*Drying afterwards makes sure streaky marks aren't left behind.

*Wiping with a damp cloth is basically ineffective, as it can smear dirt without removing it.

*Routine cleaning prevents any stubborn stains building up.

WHAT TO USE:-

For day to day cleaning, plenty of water, some very mild detergent and a cloth or soft brush will do the job.

After washing, thoroughly rinse with clean water and wipe the surface dry with a soft absorbent cloth.

On brushed Stainless Steel, Zinc Alloy Diecast, follow the direction of the grain for best results. An excellent cloth to use is 3M's Scotch-Brite high performance cleaning cloth.

AVOID SCRATCHES!

Remember, Stainless Steel, Zinc Alloy Diecast or ABS can be scratched by careless handling or aggressive scrubbing. Avoid dragging rough items across the surface and be aware that grit, trapped under other materials, can actually cause surface scratches.

HANDLING TOUGH MARKS & STAINS

Here's how to get rid of the most common tough marks: Fingerprints, oil & grease marks If a mild detergent or dishwashing detergent doesn't shift unsightly fingermarks, eliminate them with a quality glass cleaner on a soft cloth. Also, use of a small amount of alcohol, methylated spirits, acetone or mineral turpentine will remove these type marks. Thoroughly rinse with clean water and dry.

REMOVING STICKY LABELS

Remove sticky labels as soon as possible.

Gentle heat from a hair dryer or a glue gun generally softens the glue for easy removal Eucalyptus oil based cleaners (or eucalyptus oil on its own) often work well to remove adhesives.

Ensure you don't leave any glue on the surface – it could trap dirt or break down and cause staining.

NEVER EVER USE...

*steel wool (wire wool) to clean either ABS or Zinc Alloy Diecast.

* pre-used scourer

* Stainless steel wool scouring pads are available for heavy duty work, These will scratch the Zinc Alloy Diecast.

TOTALLY AVOID

* Any water or substances penetrating the interior of the Hand Dryer

- * Rubbing with steel wool (wire wool) or scraping with steel tools
- * Using scourers
- * Rubbing plastic scourers across the grain of brushed surfaces
- * Using concentrated bleach or hydrochloric acid-based cleaning
- * Contact with product containing chlorine bleach, hydrochloric or muriatic acid

The technical recommendations contained in this document are necessarily of a general nature and should not be relied on for specific applications without first securing competent advice. Whilst Metlam Australia Pty Ltd has taken all reasonable steps to ensure the information contained herein is accurate and current, and in accordance with ASSDA recommendations, it does not warrant the accuracy or completeness of the information and does not accept liability for errors or omissions.

Any Commercial Stainless Steel, Zinc Alloy Diecast or ABS product should only be installed by a competent

tradesperson and serviced/maintained by knowledgeable janitorial staff or competent people. Metlam Australia accepts no responsibility for any damage to product, walls or fixtures due to incorrect installation or maintenance of any of their products.

The photographs and line drawings of the products presented above are representational only. Metlam Australia Pty Ltd reserves the right to, and from time to time, make changes and improvements in design and dimensions.

Metlam Australia Pty Ltd Tel: 61 3 5428 4618 Fax: 61 3 5428 1780 Email: sales@metlam.com.au www.metlam.com.au